Work Orde		085		*82	185 *						Page 1	
Revision ID:	D412-702-30 Harness Assen		,	Accept	*N900	040	100)* s	Setup Star	IVI	S1* S2*	
Start Date: Required Date: Reference:	22/03/2012 05/04/2012	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item I Customer:	D:						
Approvals:		in: _ML5	1 1	Tooling: SPC (Y/N):		ate:		F	Run Star Sto	" [\]	R1* R2*	
Sequence ID/ Work Center II)	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
Draw Nbr	Rev	ision Nbr										
ICAD412-702	4										N	•
*100 *100* Small Fab		Memo		0.00				/X_			1,2/0	1 / 16/04
Small Fab		Assemble as	s per dwg ICA D412-702 p.	49								
*110 *110*		QC5- Inspect part compl	leteness to step on W/O	0.00	7/06/06			(d)				
QC Quality Control		Memo		0.00						·		
120				0.00								
120 Packaging				0.00				/			(12/06/	0 >
Packaging		Memo Identify with	h P/N & CHG# and pack for		0412-702-307						·	,
		CHG001 Location: <u>5</u> PPP Rev:		A.	*							

Dart Aerospace	Ltd	
----------------	-----	--

Dart Aeı	rospace	Ltd							
W/O:			W	ORK ORDER CHANGES			**************************************		
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		`							
				· · · · · · · · · · · · · · · · · · ·					
Part No	:	PAR #:	Fault Cate	gory: N	CR: Yes	No DQ	A :	Date: _	
	Re	esolution:	Dispositio	on: G	A: N/C Cl	osed:		Date: _	
NCR:		1	WORK ORD	ER NON-CONFORMANO	E (NCR)			
DATE	STEP	Description of NC		Corrective Action Section B		Verific	ation	Approval	Approval
	O.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	on C	Chief Eng	QC Inspector
						:			
	·								
									·
							<u>-</u>		
					·				
 i		•					<u>.</u>		

	Work Order ID 82085 March-22-12 2:22:22 PM			*82085*								Page 2
Item ID: Revision ID: Item Name:	D412-702-3 Harness Asset			Accept	*N900	040	100)*	Setup	Start Stop	1 7	S1* S2*
Start Date: Required Date Reference:	22/03/2012 : 05/04/2012	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item I Customer:	D:						
Approvals:	Process Pla	ın:	Date:	Tooling: SPC (Y/N):		ate:			Run	Start Stop	*N *N	R1* R2*
Sequence ID/ Work Center I 130 *130* QC Quality Control	D	Operation Description QC21- Final Inspection Memo	- Work Order Release	Set Up/ Run Hours 0.00	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp

V1204-7

Dart Aerospace Ltd

		<u> </u>									
W/O:			W	ORK ORDER CHANGE	S						
DATE	STEP	PRO	CEDURE CHA	ANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
		777									
<u> </u>											
Part No	·	PAR #:	_ Fault Cate	egory:	NCR: Yes No DQA: Date:						
		esolution:									
NCR:		W	ORK ORD	ER NON-CONFORMA	NCE (NCR)						
DATE	STEP	Description of NC		Corrective Action Section		Verification	Approval	Approval			
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector			
·								-			
•											
				*,			[
	·										
·											
					•						
***	1	•				1		İ			

Picklist Print

March-22-12 2:22:26 PM

Work Order ID: 82085

82085

Parent Item:

D412-702-307

D412-702-307

Parent Item Name: Harness Assembly

Start Date: 22/03/2012

Required Date: 05/04/2012

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP Rev:A new issue DD 10.04.30 verified:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3573-3		Manufactured	No			100	Each	3.0000	1	1 /	01		
D3573-3									**	4	12	106	104
				Location	1	Loc	<u>Oty</u>	Loc Code				ι	
				GA			3		_		_ 2	8048	
					69462		3		_			0090	5 4
D4088-041		Manufactured	No			100	Each	11.0000	1	1 (/
D4088-04 Shoulder Harness	1								**	4	Sidf	<u>vc/c</u>) Y
				Location	1	<u>Loc</u>	<u>Qty</u>	Loc Code				_	
				ST267			11			/	_	R80	45
					75443		11		_				, 5 /
MS24693-S272		Purchased	No			100	Each	373.0000	4	4 2	?[/ /	/
MS24693-	-S272								**	9.	02	106/0	24
				Location	!	Loc	<u>Qty</u>	Loc Code			·	l	
				GA			332						*
					118352		332		_	4_			
				ST288			41		_		_		
					116391		11		_		_		
					116737		2		_		_		
					117977		28		_		_		

Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANG	BES									
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
							-							
Part No	•	PAR #:	Fault Ca	tegory:	_ NCR: Yes	No DQ	A:	Date: _						
	R	Resolution: Disposition:				QA: N/C Closed: Date:								
NCR:			VORK OR	DER NON-CONFORM	ANCE (NC	R)								
DATE	STEP	Description of NC Section A	Initial	Action Description	tion B Sign	& Sect	cation ion C	Approval Chief Eng	Approval QC Inspector					
	١.		Chief Eng	Chief Eng	Date	•								
			·											
		1			1									
	1	1	1		l l	1		i .						

Picklist Print

March-22-12 2:22:26 PM

Page 2

Work Order ID: 82085

Parent Item Name: Harness Assembly

82085

D412-702-307

D412-702-307

Start Date: 22/03/2012

Required Date: 05/04/2012

Start Qty: 1.00

Required Qty: 1.00

AN960JD10LL

Parent Item:

Purchased

No

100

3,597.000 Each

**

*AN960.ID1011 *

Washer

Location Loc Qty ST337A 3597 19085 368 19600 3229 Each

Loc Code

MS21042L3

Purchased

No

100

2,843.000


**

MS21042L3


Location	Loc Qty	Loc Code
ST300	2843	
117441	16	
117885	32	
118451	5	
118927	3	
119017	2621	
119075	166	

Dart Aero	space Ltd
------------------	-----------

							A: Date:	
			ORK ORDER CHANGE	ES				
DATE	ATE STEP Resolution: CR: Description	PRO	CEDURE CH	ANGE	Ву	Date Qt	Chief Eng /	Approval QC inspector
		,						
	PAR #: Fault Category: NCR: Yes No DQA: Resolution: Disposition: QA: N/C Closed:							
Part No:PAR #: Fault Category:NCR: Resolution:Disposition:QA: N NCR: WORK ORDER NON-CONFORMANCE (DATE STEP Description of NC Section A Chief Eng Action Description Section B								
Part No	:	PAR #:	Fault Cate	egory:	NCR: Yes	No DQA:	Date: _	
		esolution:	Disposition	on:	QA: N/C Clo	sed:	Date: _	
NCR:			WORK ORDER NON-CONFO)		
DATE	STED	Description of NC				Verificatio		Approval
DAIL	O.L.	Section A	1		Sign & Date	Section C	Chief Eng	QC Inspector
_	•							
		·						



<u>DETAIL 'K' D412-702-101A/-103A/-105A/-107A/-109A/-115A/-117A AND</u> <u>D412-702-101B/-103B/-105B/-107B/-109B/-115B/-117B OR -301/-303/-305/-307/-309/-315/-317 HARNESS ASSEMBLIES</u>



DETAIL 'L' D412-702-111A/-111B/-113A/-113B OR -311/-313/-321/-323 HARNESS ASSEMBLIES

COPYRIGHT © 2004 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Dart Aerospac	e Lte	d
---------------	-------	---

-u	Johade	Live													
W/O:			W	ORK ORDER CHANG	GES										
DATE STEP Part No:	PRO	OCEDURE CH	ANGE	В	/	Date	Qty	Approval Chief Eng / Prod Mgr	Approvai QC Inspector						
	Part No:														
	:														
Part No:			· · · · · · · · · · · · · · · · · · ·				*								
			4												
			PAR #: Fault Category:					NCR: Yes No DQA: Date:							
		esolution:	Dispositi	on:	QA: N/	C Clos	sed:		Date: _						
NCR:			WORK ORDER NON-CONFOR												
DATE	STEP	Description of NC		10.0	tion B		cation	Approval	Approval						
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date				Chief Eng	QC Inspector					
					·										